


acer



NITRO 5





| | | |
|---------------------------------|--|---|
| Product views | <ol style="list-style-type: none"> 1. USB Type-C™ port (USB 3.2 Gen 2x2) 2. USB 3.2 Gen 2 port 3. Headset / speaker jack 4. Microphone jack 5. Power button 6. Wireless charger | <ol style="list-style-type: none"> 7. Two USB 2.0 ports 8. Two USB 3.2 Gen 1 ports 9. Two USB 2.0 ports 10. Audio jacks 11. Ethernet (RJ-45) port 12. Power connector |
| Operating system | Windows 11 Home 64-bit | |
| CPU and chipset | Intel® Core™ i5-14400F 14th gen processors, 10 (6P+4E) Core Processor Chipset: Intel® B760 Chipset | |
| Memory | 16 GB DDR5 4800 MHz UDIMM ● Up to 32 GB of Dual-channel DDR5 | |
| Storage | Hard disk drive ● 512 GB M.2 2280 PCIe Gen4 SSD | |
| Graphics | NVIDIA® GeForce® RTX™ 4060 with 8 GB of GDDR6 (1xHDMI, 3xDP) | |
| Audio | DTS:X® Ultra | |
| Communication | WLAN ● 802.11ax/ac/a/b/g/n, Wi-Fi 6E and Bluetooth® 5 LAN ● Realtek® 8118AS Dragon Gigabit Ethernet | |
| Expansion slot(s) | ● PCIe x16 slot(s): 1 ● PCIe x1 slot(s): 1 ● M.2 slot (for SSD): 2 ● M.2 slot (for WLAN): 1 | |
| Dimensions | 175 (W) x 386 (D) x 392 (H) mm | |
| Power supply and adapter | Power supply ● 500 W PFC, auto-sensing, 80PLUS® Gold, ATX | |
| Windows Desktop Apps | In-House ● Acer Care Center ● Acer Configuration Manager ● Acer Product Registration ● Acer User Experience Program Framework ● Power Management Setting ● Quick Access ● Storage Utilities Search ● NitroSense | Security ● McAfee LiveSafe P2 |
| System compliance | RoHS, ENERGY STAR® | |
| Options and accessories | | |
| Certification | BSMI, VCCI, CCC, CE, FCC, CB | |

As a phenomenon known to thin-film transistors (TFTs), liquid crystal displays (LCDs) commonly exhibit a small number of discoloration dots, as so-called "non-conforming pixels." This phenomenon is a limitation of TFT LCD technology, not a product defect, and as such is not covered by Acer's warranty. In a continuing effort to improve the quality of our products, information in this document is subject to change without notice. Images shown are only representations of some of the configurations available for this model. Availability may vary depending on region.

© 2023. All rights reserved.

Microsoft and Windows are registered trademarks of Microsoft Corporation.

Ultrabook, Celeron, Celeron Inside, Core Inside, Intel, Intel Logo, Intel Arc graphics, Intel Atom, Intel Atom Inside, Intel Core, Intel Inside, Intel Inside Logo, Intel vPro, Intel Evo, Pentium, Pentium Inside, vPro Inside, Xeon, Xeon Inside, Intel Agilix, Arria, Cyclone, Movidius, eASIC, Ethernet, Iris, Killer, MAX, Select Solutions, Si Photonics, Stratix, Tofino, and Intel Optane are trademarks of Intel Corporation or its subsidiaries.

About Acer

Founded in 1976, Acer is one of the world's top ICT companies with a presence in more than 160 countries. As Acer evolves with the industry and changing lifestyles, it is focused on enabling a world where hardware, software and services will fuse with one another, creating ecosystems and opening up new possibilities for consumers and businesses alike. Acer's 7,500 employees are dedicated to the research, design, marketing, sale, and support of products and solutions that break barriers between people and technology. Please visit www.acer.com for more information.